


WIRING DIAGRAM



1980 BLIZZARD 5500